

VITA Family Global Reset

AND9049/D

Application Note Abstract

This application note explains the need for the extra reset of the storage node. This applies only to global shutter operating modes.

Problem Statement

Under certain circumstances, global shutter images taken by VITA sensors contain bright pixels. There can be several reasons for this: leakage or changing sequencer modes.

1. Leakage

In a global shutter, after exposure the integrated charge from each pixel is transferred to the pixel storage node. Since this is typically diffusion, it has some leakage. The storage nodes of some pixels are leakier than others, resulting in the bright spots that can be seen in images with larger frame times and the default timing.

The figure below shows the frame overhead time (gray), the row overhead time (red) and the line read time (green) for a frame of 6 lines. Note that it is not to scale. The upper part of the image shows the general case with the master global shutter mode. The storage node of each row is reset during the row overhead time of the previous frame. The time

between 2 resets of the floating diffusion is therefore equal to 1/frame rate.

Typically, in triggered mode, there can be a significant time between two frames (low frame rate) and then the storage node will have much time to leak. But it is not limited to triggered mode, one can program the fr_length and mult_timer registers to have large frame times as well.

The frame time can be dominated either by the integration time or by the read out time (Figure 2) or by the requested frame rate (Figure 1). Typically, the former will be the case for small windows, where the readout time is small; the middle case happens for short integration times or for the CMOS out version since it takes 4x more time to readout a frame compared to the LVDS version.

In some cases (high frame time), it is better to do a global reset of the storage node in the FOT. The relevant time where leakage can occur is different for every line. The last line is the worst. In this case, the maximum time the storage node can leak is the readout time of the frame. The readout time is now relevant, not the frame time. It is pictured in the lower part of Figure 1.




Figure 1. Comparison of Both Timings for an Application that is not Readout Time Limited

The extra global reset does increase the total frame overhead time, therefore reducing the maximum frame rate (shown in Figure 2). For full frame images, this has a very

limited impact; for a small window this can be dominant, but when frame rate is important, the frame time shall be small

AND9049/D

anyway and PSNL is not an issue, so the normal timing will do just fine.

When to use what timing? In the example above, it would be better to use the timing with global reset since the read out

time is \ll frame time. In the example below, however, the read out time is dominant and there is no need for the extra reset and the frame rate is reduced.




Figure 2. Comparison of Both Timings for an Application that is Readout Time Limited

In conclusion, there is no optimal timing for all applications. One should choose the best timing for the intended application.

2. Sequencer operation mode changes

Newly activated windows containing image lines which haven't been read in the previous frame also suffer from the fact that the corresponding storage nodes haven't been reset, or have been reset a significant time in the past. Therefore, the first frame after such a window change needs to be discarded.

Similarly, the first full readout after a subsampled readout suffers from the same artifacts (odd lines are brighter than the even lines).

These problems are also avoided by globally resetting all storage nodes during frame overhead.

It is recommended to activate the timing mentioned in this application note when it is required to frequently reposition the windows or to switch between subsampled and normal readout modes without losing frames.

IMPLEMENTATION FOR VITA1300

Globally resetting the storage nodes requires a different internal timing that should be uploaded through the SPI. These are of the same kind as the "required register uploads" as specified in the data sheet. The settings given below

override whatever is mentioned in the data sheet for those registers. Any registers specified in the data sheet that are not mentioned here, remain valid.

Upload #	Address	Data	Description
1	384	0x1010	Reserved
2	385	0x729F	Reserved
3	386	0x729F	Reserved
4	387	0x729F	Reserved
5	388	0x729F	Reserved

AND9049/D

Upload #	Address	Data	Description
6	389	0x701F	Reserved
7	390	0x701F	Reserved
8	391	0x549F	Reserved
9	392	0x549F	Reserved
10	393	0x541F	Reserved
11	394	0x541F	Reserved
12	395	0x101F	Reserved
13	396	0x101F	Reserved
14	397	0x1110	Reserved

IMPLEMENTATION FOR VITA2000 AND VITA5000

Globally resetting the storage nodes requires a different internal timing that should be uploaded through the SPI. These are of the same kind as the “required register uploads” as specified in the data sheet. The settings given below overrule whatever is mentioned in the data sheet for those

registers. Any registers specified in the data sheet that are not mentioned here, remain valid.

Note that these uploads increase the ROT significantly, reducing the max frame rate. Usually, this shouldn't be a concern.

Upload #	Address	Data	Description
1	384	0x1010	Reserved
2	385	0x729F	Reserved
3	386	0x729F	Reserved
4	387	0x729F	Reserved
5	388	0x729F	Reserved
6	389	0x701F	Reserved
7	390	0x701F	Reserved
8	391	0x549F	Reserved
9	392	0x549F	Reserved
10	393	0x541F	Reserved
11	394	0x541F	Reserved
12	395	0x101F	Reserved
13	396	0x101F	Reserved
14	397	0x1110	Reserved
15	219	0x412E	Reserved
16	430	0x0100	Reserved
17	431	0x03F1	Reserved
18	432	0x03C5	Reserved
19	433	0x0341	Reserved
20	434	0x0141	Reserved
21	435	0x214F	Reserved
22	436	0x2145	Reserved
23	437	0x0141	Reserved
24	438	0x0101	Reserved
25	439	0x0B8C	Reserved

AND9049/D

Upload #	Address	Data	Description
26	440	0x0B8C	Reserved
27	441	0x0B8C	Reserved
28	442	0x0B8C	Reserved
29	443	0x0381	Reserved
30	444	0x0181	Reserved
31	445	0x218F	Reserved
32	446	0x2185	Reserved
33	447	0x0181	Reserved
34	448	0x0100	Reserved
35	449	0x0100	Reserved
36	450	0x0BF1	Reserved
37	451	0x0BC3	Reserved
38	452	0x0BC2	Reserved
39	453	0x0341	Reserved
40	454	0x0141	Reserved
41	455	0x214F	Reserved
42	456	0x2145	Reserved
43	457	0x0141	Reserved
44	458	0x0101	Reserved
45	459	0x0B8C	Reserved
46	460	0x0B8C	Reserved
47	461	0x0B8C	Reserved
48	462	0x0B8C	Reserved
49	463	0x0381	Reserved
50	464	0x0181	Reserved
51	465	0x218F	Reserved
52	466	0x2185	Reserved
53	467	0x0181	Reserved
54	468	0x0100	Reserved
55	194[10]	0x0	Reserved
56	72[14:12]	0x3	Optimize CP setting
57	70[8:6]	0x3	Only required on VITA5000

AND9049/D

IMPLEMENTATION FOR VITA25K

The same as for the other vita sensors applies here. However, since this pixel array is much bigger, the sensor may have increased row fpn compared to normal operation mode. This can be fixed by the changes in table below. Note that these uploads increase the ROT significantly, reducing

the max frame rate. Usually, this shouldn't be a concern because there is no need to have global reset when running the sensor at max frame rate. If it is a concern, zero ROT should be used.

Upload #	Address	Data	Description
1	384	0x1010	Reserved
2	385	0x729F	Reserved
3	386	0x729F	Reserved
4	387	0x729F	Reserved
5	388	0x729F	Reserved
6	389	0x701F	Reserved
7	390	0x701F	Reserved
8	391	0x549F	Reserved
9	392	0x549F	Reserved
10	393	0x541F	Reserved
11	394	0x541F	Reserved
12	395	0x101F	Reserved
13	396	0x101F	Reserved
14	397	0x1110	Reserved
15	219	0x412E	Reserved
16	430	0x0100	Reserved
17	431	0x03F1	Reserved
18	432	0x03C5	Reserved
19	433	0x0341	Reserved
20	434	0x0141	Reserved
21	435	0x214F	Reserved
22	436	0x2145	Reserved
23	437	0x0141	Reserved
24	438	0x0101	Reserved
25	439	0x0B8C	Reserved
26	440	0x0B8C	Reserved
27	441	0x0B8C	Reserved
28	442	0x0B8C	Reserved
29	443	0x0381	Reserved
30	444	0x0181	Reserved
31	445	0x218F	Reserved
32	446	0x2185	Reserved
33	447	0x0181	Reserved
34	448	0x0100	Reserved
35	449	0x0100	Reserved
36	450	0x0BF1	Reserved

AND9049/D

Upload #	Address	Data	Description
37	451	0x0BC3	Reserved
38	452	0x0BC2	Reserved
39	453	0x0341	Reserved
40	454	0x0141	Reserved
41	455	0x214F	Reserved
42	456	0x2145	Reserved
43	457	0x0141	Reserved
44	458	0x0101	Reserved
45	459	0x0B8C	Reserved
46	460	0x0B8C	Reserved
47	461	0x0B8C	Reserved
48	462	0x0B8C	Reserved
49	463	0x0381	Reserved
50	464	0x0181	Reserved
51	465	0x218F	Reserved
52	466	0x2185	Reserved
53	467	0x0181	Reserved
54	468	0x0100	Reserved
55	197[7:0]	0x0015	At least 21 black lines.
Supply change #	Name	Value [V]	
1	vdd_resfd	4.2	

onsemi, **Onsemi**, and other names, marks, and brands are registered and/or common law trademarks of Semiconductor Components Industries, LLC dba "**onsemi**" or its affiliates and/or subsidiaries in the United States and/or other countries. **onsemi** owns the rights to a number of patents, trademarks, copyrights, trade secrets, and other intellectual property. A listing of **onsemi**'s product/patent coverage may be accessed at www.onsemi.com/site/pdf/Patent-Marking.pdf. **onsemi** reserves the right to make changes at any time to any products or information herein, without notice. The information herein is provided "as-is" and **onsemi** makes no warranty, representation or guarantee regarding the accuracy of the information, product features, availability, functionality, or suitability of its products for any particular purpose, nor does **onsemi** assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation special, consequential or incidental damages. Buyer is responsible for its products and applications using **onsemi** products, including compliance with all laws, regulations and safety requirements or standards, regardless of any support or applications information provided by **onsemi**. "Typical" parameters which may be provided in **onsemi** data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. **onsemi** does not convey any license under any of its intellectual property rights nor the rights of others. **onsemi** products are not designed, intended, or authorized for use as a critical component in life support systems or any FDA Class 3 medical devices or medical devices with a same or similar classification in a foreign jurisdiction or any devices intended for implantation in the human body. Should Buyer purchase or use **onsemi** products for any such unintended or unauthorized application, Buyer shall indemnify and hold **onsemi** and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that **onsemi** was negligent regarding the design or manufacture of the part. **onsemi** is an Equal Opportunity/Affirmative Action Employer. This literature is subject to all applicable copyright laws and is not for resale in any manner.

ADDITIONAL INFORMATION

TECHNICAL PUBLICATIONS:
Technical Library: www.onsemi.com/design/resources/technical-documentation
onsemi Website: www.onsemi.com

ONLINE SUPPORT: www.onsemi.com/support
For additional information, please contact your local Sales Representative at
www.onsemi.com/support/sales